

71.4685.583 Rubber Metal Buffer (Hub Carrier Bush)



71.4685.583

Rubber Metal Buffer (Hub Carrier Bush)

M10x1.5/Å~58x36.5

VEHICLE	OE
SCANIA	329 583
SCANIA	305 345