

# 71.1585.095 Rubber Metal Buffer (Hub Carrier Bush)

---



**71.1585.095**

Rubber Metal Buffer (Hub Carrier Bush)

**VEHICLE**

**OE**

SCANIA

222 095